



3D Projections

- Override Model View Options
- Opening Line

Line Orientation

- Handle
- Hinges

Opening Side: Dashed

Opposite Side: Solid Line

3

2D Symbol					
3D Back View inside		 wrong arrow direction wrong linetype		 wrong arrow direction wrong linetype	 outside
3D Front View outside		 wrong arrow direction wrong linetype		 wrong arrow direction wrong linetype	

CASINGS MISSING IN ALL SCHEDULE VIEWS

